# Disposable 1870+ N95

1

Remove respirator from its packaging and hold with straps facing upward.

2

Fully open the top and bottom panels. Straps should separate when panels are opened. Make certain the bottom panel is unfolded and completely opened

3

Place the respirator on your face, so that the foam rests on your nose and the bottom panel is securely under your chin.

4

Pull the top strap over your head resting it high at the back of your head. Then, pull the bottom strap over your head and position it around your neck.

5

Adjust for comfort by pulling the top panel toward the bridge of your nose and position the bottom panel under your chin.

6

Place fingertips from BOTH hands at the top of your nose and bold the nosepiece to achieve a secure seal. **Do NOT pinch!**

Please Note:

Check the seal of your three-panel facepiece respirator each time you don the respirator.

Place one or both hands completely over the middle panel. Inhale and exhale sharply. If air leaks around your nose, readjust the nosepiece. If air leaks between the face and faceseal of the respirator, reposition it by adjusting the panels and straps. If you cannot achieve a proper seal, do not enter the contaminated area. See your supervisor.

REMOVAL INSTRUCTIONS

Without touching the respirator, slowly lift the bottom strap from around your neck up and over your head.

Lift off the strap on top of your head. Do NOT touch the respirator

Mask is suitable to wear for three or more days.

Reminder:

You must be fit tested ANNUALLY to stay in compliance with UMMC's policy and for your own SAFETY!

N95'S Limitations:

- ☐ N95's do NOT provide oxygen. Do NOT use in an oxygen deficient atmosphere.
- ☐ N95's do NOT protect against chemical challenges (cleaning solvents
- ☐ N95's are a single user item – do NOT share with others!

Contact the Safety Dept. via 1Call if you have any questions or concerns. You can also find more safety-related materials on our
Safety & Environmental Health Intranet page